

Parcel Map Check Report

Date: 5/22/2019 3:35:49 PM

Parcel Name: Site 1 - 1

Description:

Process segment order counterclockwise: False

Enable mapcheck across chord: False

Client:

Prepared by:

North: 1,700,382.840'

East: 3,206,180.678'

Segment# 1: Line

Course: S83°28'32"E

Length: 431.98'

North: 1,700,333.755'

East: 3,206,609.861'

Segment# 2: Curve

Length: 15.94'

Radius: 11.00'

Delta: 83°00'22"

Tangent: 9.73'

Chord: 14.58'

Course: S41°58'21"E

Course In: S6°31'28"W

Course Out: N89°31'50"E

RP North: 1,700,322.826'

East: 3,206,608.611'

End North: 1,700,322.916'

East: 3,206,619.610'

Segment# 3: Line

Course: S0°28'10"E

Length: 721.38'

North: 1,699,601.561'

East: 3,206,625.521'

Segment# 4: Line

Course: S89°31'47"W

Length: 247.45'

North: 1,699,599.530'

East: 3,206,378.079'

Segment# 5: Line

Course: S0°02'35"E

Length: 23.00'

North: 1,699,576.530'

East: 3,206,378.096'

Segment# 6: Line

Course: S89°57'35"W

Length: 196.79'

North: 1,699,576.391'

East: 3,206,181.306'

Segment# 7: Line

Course: N0°02'39"W

Length: 806.45'

North: 1,700,382.841'

East: 3,206,180.685'

Perimeter: 2,443.00'

Area: 338,979Sq.Ft.

5/22/2019

Parcel Map Check Report

Error Closure: 0.007

Course: N78°10'21"E

Error North : 0.0014

East: 0.0065

Precision 1: 348,998.57